

GENERAL NOTES:

- BACKFLOW PREVENTER MUST BE ACCESSIBLE DOWNSTREAM OF METER. FOR TESTING AND INSTALLED NEAR PROPERTY
- . N LINE DOWNSTREANO TAPS, TEES METER AND THE BACKFLOW ASSEMBLY. 0 R CONNECTIONS OF ANY KIND ARE PERMITTED BETWEEN HE WATER
- 7 PROTECTION FROM FREEZE DAMAGE MAY BE REQUIRED IN EXPOSED AREAS.
- 4. ASSEMBLY MUST BE ACCESSIBLE FOR TESTING MUNICIPAL CODE. AND MAINTENANCE PER MADERA
- 5 ASSEMBLY TO BE PLUMBING CODE. THE SAME SIZE AS THE WATER SUPPLY PER UNIFORM
- <u>0</u> PRESSURE LOSS CALCULATIONS FOR SIZING OF THROUGH ASSEMBLY MUST BE INCLUDED IN PRESSURE LOSS THE WATER SYSTEM PER UNIFORM PLUMBING CODE.
- 7. MINIMUM CLEARANCES AROUND ASSEMBLY MUST BE MAINTAINED. REFER TO MINIMUM
- \odot THE ASSEMBLY - 3/4 THRU 2" CLEARANCE CHART ON THIS PAGE.

 NSTALL A MINIMUM OF ONE UNION 0 N E UNION IN THE PIPING SIZES. SYSTEM WITHIN <u>-</u> INCHES OF
- DRAINAGE TO EXTERIOR INSTALLED INSIDE. OF THE BUILDING IS REQUIRED WHEN ASSEMBLY
- <u>1</u>0. DEPARTMENT DOUBLE OF CHECK BACKFLOW PREVENTION HEALTH SERVICES. ASSEMBLIES MUST \mathbb{H} APPROVED ВҮ СА

DOUBLE CHECK DETECTOR
ASSEMBLY (DCDA) BACKFLOW
PREVENTOR CLASS I — II

REF. & REV. MARCH 2005 MAY 2007

CITY OF MADERA